

Introducing Process Improvement To New Employees



November 9,
2021



Meet the Presenters



Shreya Gautam

Application Specialist
PQ Systems



Derek Benson




Product & Application Support Manager
PQ Systems







First day on the job...



Standard Operation Sheet

faurecia		STANDARD OPERATION			PAU-P-PS-241 / EN REV 02	Plant:	Washington	Document No.:	XXXX
Part Number	xxx	PartName	Bolster	Line :	EQ Bolster	Work-station:	Woodstock	Revision Level:	4
No.	Operation	+ = SAFETY	◆ = QUALITY	● = TIP	Time :	Sketches / Photo's / etc.			
1	Remove parts from tool				30 Sec				
2	Remove the spiking frame from the upper tool			●					
3	Fold waste and place onto to stand.								
4	Remove the spiked frame from the underneath bench		◆						
5	Place one white & green clip into cavities 3&4			●					

Issued	Signature/Date	Checked	Signature/Date	Approved	Signature/Date	SKILLED OPERATOR	Signature/Date	Non Conforming Product	
Name:		Name:		Name:		Name:		Place rejects in reject container. Record on Process Monitor Sheet. If 3 or more rejects found with same fault call Gap Leader.	
Function:		Function:		Function:		Function:			



Header information

**VARIABLES CONTROL CHART
X - MR CHART**

Quality measure *Sales \$* Chart no.



Product / Service *Food service* Process *Restaurant* Specification limits







User name *Joan Rogers* Location *Sherman* Measurement device *Sales receipts* Unit of measure *\$1,000*

DATE	Aug 5	Aug 12	Aug 19	Aug 26	Sep 2	Sep 9	Sep 16	Sep 23	Sep 30	Oct 7	Oct 14	Oct 21	Oct 28	Nov 4	Nov 11	Nov 18	Nov 25	Dec 2	Dec 9	Dec 16	Dec 23	Dec 30	Jan 6	Jan 13	Jan 20	
TIME	<i>8p.m.</i>																									
SAMPLE MEASUREMENT	1	90	97	118	108	112	105	106	102	100	100	102	121	108	107	106	96	102	103	105	103	94	92	107	89	112
MOVING RANGE, M R		7	21	10	4	7	1	4	4	6	2	19	13	1	1	10	6	1	2	2	9	2	15	18	23	
NOTES																										

Data

Individual chart










Policies

Procedure

New Employee Onboarding



Introducing... The 5 Step plan



1. Learn “What we do”



Pretend with us...



We make Paddles

Each Paddle has 30 dimples to catch beads

These paddles are designed to capture 7 red beads on each dip into a bucket full of both red and white beads.

We're all different..





Maybe it doesn't fit all?

What do they know?




What don't they know?

Experience with Quality?

Experience with Manufacturing?

Experience with our products?

2. Inspection



“These parts have to be made to print”

“We cannot ship non-conforming parts to the customer”


“Let’s make sure all our data is in spec”



100%



In the case of our Red-Bead Paddle Factory...



Good



Bad




What do you do with the bad ones?

In manufacturing, how much money is spent/lost each year in the form of waste?

\$8 trillion

#1 Contributor to the waste..



Defects



We hired you to find and quarantine the defects.




The customer receives all good paddles.


Everyone is happy!



Prevention over Inspection



3. Understanding Variation



Statistical Process Control (SPC) is the use of statistical tools to monitor production processes in order to **prevent** defective product.

Organizations that implement an SPC program move beyond the costly quality control method of **inspecting** for waste.

An SPC program allows manufacturers to identify the possibilities for product flaws early so that they can prevent producing scrap.

Find the Special-Cause Variation



UNDERCONTROLLING

Treating special-cause variation as common-cause
(Failing to make changes when they were necessary)

OVERCONTROLLING

Treating common-cause variation as special-cause
(Making changes when none were necessary)



When is it used?

Answer “yes” to each of the following:

- Do you need to assess the variability in the system?
- Can the data be collected or does a collection of data already exist?
- Is the time order of the data preserved?
- Is the data in variables format?
- Is the data collected in subgroups of one?



Pen and paper!



X-MR Control Chart



How is it made?

1. Complete the header information.
2. Record the data.
3. Calculate the moving ranges.
4. Calculate the overall averages.
5. Calculate the control limits.
6. Scale the control chart.
7. Draw the average line and control limits.
8. Plot the values on the control chart.
9. Interpret the control chart.



X-MR Control Chart

How is it made?

1. Complete the header information.
2. Record the data.
3. Calculate the moving ranges.
4. Calculate the overall averages.
5. Calculate the control limits.
6. Scale the control chart.
7. Draw the average line and control limits.
8. Plot the values on the control chart.
9. Interpret the control chart.



X-MR Control Chart

How is it made?

1. Complete the header information.
2. Record the data.
- 3. Calculate the moving ranges.**
4. Calculate the overall averages.
5. Calculate the control limits.
6. Scale the control chart.
7. Draw the average line and control limits.
8. Plot the values on the control chart.
9. Interpret the control chart.



X-MR Control Chart

How is it made?


1. Complete the header information.
2. Record the data.
3. Calculate the moving ranges.
- 4. Calculate the overall averages.**
5. Calculate the control limits.
6. Scale the control chart.
7. Draw the average line and control limits.
8. Plot the values on the control chart.
9. Interpret the control chart.



X-MR Control Chart

How is it made?

1. Complete the header information.
2. Record the data.
3. Calculate the moving ranges.
4. Calculate the overall averages.
- 5. Calculate the control limits.**
6. Scale the control chart.
7. Draw the average line and control limits.
8. Plot the values on the control chart.
9. Interpret the control chart.






X-MR Control Chart

How is it made?


1. Complete the header information.
2. Record the data.
3. Calculate the moving ranges.
4. Calculate the overall averages.
5. Calculate the control limits.
- 6. Scale the control chart.**
- 7. Draw the average line and control limits.**
- 8. Plot the values on the control chart.**
9. Interpret the control chart.



X-MR Control Chart

How is it made?

1. Complete the header information.
2. Record the data.
3. Calculate the moving ranges.
4. Calculate the overall averages.
5. Calculate the control limits.
6. Scale the control chart.
7. Draw the average line and control limits.
8. Plot the values on the control chart.
9. Interpret the control chart.



X-MR Control Chart

9. Interpret the control chart.

- *Basic rules for interpretation*
 - Any point lying outside the control limits.
 - Run of seven points:
 - » Seven or more points in a row above or below the center line.
 - » Seven or more points in a row going in one direction, up or down.
 - Any non-random pattern, including the following typical cases:
 - » Too close to the average.
 - » Too far from the average.
 - » Cycles.

Rules for: **AIAG**

Name
Beyond limits
7 ascending
7 descending
7 above centerline
7 below centerline

Rules for: **Western**

Name
Beyond limits
2 of 3 beyond 2 sigma
4 of 5 above 1 sigma
4 of 5 below 1 sigma
8 above centerline
8 below centerline

Rules for: **Hughes**

Name
Beyond limits
2 of 3 above 2 sigma
2 of 3 below 2 sigma
3 of 7 above 2 sigma
3 of 7 below 2 sigma
4 of 10 above 2 sigma
4 of 10 below 2 sigma
7 above centerline
7 below centerline
10 of 11 above centerline
10 of 11 below centerline
12 of 14 above centerline
12 of 14 below centerline
7 ascending
7 descending




Rules for: **Shewhart**

Name
Beyond limits
2 of 3 above 2 sigma
2 of 3 below 2 sigma
4 of 5 above 1 sigma
4 of 5 below 1 sigma
8 above centerline
8 below centerline

Rules for: **Juran**

Name
Beyond limits
2 of 3 above 2 sigma
2 of 3 below 2 sigma
4 of 5 above 1 sigma
4 of 5 below 1 sigma
9 above centerline
9 below centerline
6 ascending
6 descending
8 beyond 1 sigma


Characteristics of the normal distribution



Since ± 3 sigma = 99.73%, each tail of the curve has the remaining 0.135% of data



Predicting the Future



4. Meeting Customer Requirements

Capable

Capable- Meaning:


**Capable : Adjective. The ability to be competent.
Being able to do something well.**



Capability indices

- Control charts are not designed for comparisons to a specification
- Capability analysis allows you to assess your ability to meet customer needs
- Capability analysis brings together the process limits (± 3 sigma) and specification limits

The two voices:




Meeting Specifications



- We need the paddles to catch 7 red beads per dip

We understand common-cause variation, so...

- 2 red beads is our minimum acceptable amount
- 12 red beads is our maximum acceptable amount



The Capability Study!





Cp and Cpk

PROCESS CAPABILITY INDICES

- ▶ play
- stop
- ▶▶ step
- ◀ rew

$$C_p = \frac{USL - LSL}{6 \times \sigma}$$

Summarize process potential to meet two-sided specification limits.



© The Red Road



$$C_{pk} = \frac{|m - \bar{\bar{x}}|}{3 \times \sigma}$$

- ▶ play
- stop
- ▶▶ step
- ◀ rew

1. Summarize process potential to meet two-sided specification limits.


2. Cpk is a penalty factor for the process's being off nominal.


I Process out of control
 • deviation too high
 • average off nominal



© The Red Road


II Process out of control
 • average off nominal








Calculate Capability



Standard Normal Table



z	x.x0	x.x1	x.x2	x.x3	x.x4	x.x5	x.x6	x.x7	x.x8	x.x9
4.0	.00003									
3.9	.00005	.00005	.00004	.00004	.00004	.00004	.00004	.00004	.00003	.00003
3.8	.00007	.00007	.00007	.00006	.00006	.00006	.00006	.00005	.00005	.00005
3.7	.00011	.00010	.00010	.00010	.00009	.00009	.00008	.00008	.00008	.00008
3.6	.00016	.00015	.00015	.00014	.00014	.00013	.00013	.00012	.00012	.00011
3.5	.00023	.00022	.00022	.00021	.00020	.00019	.00019	.00018	.00017	.00017
3.4	.00034	.00032	.00031	.00030	.00029	.00028	.00027	.00026	.00025	.00024
3.3	.00048	.00047	.00045	.00043	.00042	.00040	.00039	.00038	.00036	.00035
3.2	.00069	.00066	.00064	.00062	.00060	.00058	.00056	.00054	.00052	.00050
3.1	.00097	.00094	.00090	.00087	.00084	.00082	.00079	.00076	.00074	.00071
3.0	.00135	.00131	.00126	.00122	.00118	.00114	.00111	.00107	.00104	.00100
2.9	.0019	.0018	.0018	.0017	.0016	.0016	.0015	.0015	.0014	.0014
2.8	.0026	.0025	.0024	.0023	.0023	.0022	.0021	.0021	.0020	.0019
2.7	.0035	.0034	.0033	.0032	.0031	.0030	.0029	.0028	.0027	.0026
2.6	.0047	.0045	.0044	.0043	.0041	.0040	.0039	.0038	.0037	.0036
2.5	.0062	.0060	.0059	.0057	.0055	.0054	.0052	.0051	.0049	.0048
2.4	.0082	.0080	.0078	.0075	.0073	.0071	.0069	.0068	.0066	.0064
2.3	.0107	.0104	.0102	.0099	.0096	.0094	.0091	.0089	.0087	.0084
2.2	.0139	.0136	.0132	.0129	.0125	.0122	.0119	.0116	.0113	.0110
2.1	.0179	.0174	.0170	.0166	.0162	.0158	.0154	.0150	.0146	.0143
2.0	.0228	.0222	.0217	.0212	.0207	.0202	.0197	.0192	.0188	.0183
1.9	.0287	.0281	.0274	.0268	.0262	.0256	.0250	.0244	.0239	.0233
1.8	.0359	.0351	.0344	.0336	.0329	.0322	.0314	.0307	.0301	.0294
1.7	.0446	.0436	.0427	.0418	.0409	.0401	.0392	.0384	.0375	.0367
1.6	.0548	.0537	.0526	.0516	.0505	.0495	.0485	.0475	.0465	.0455
1.5	.0668	.0655	.0643	.0630	.0618	.0606	.0594	.0582	.0571	.0559
1.4	.0808	.0793	.0778	.0764	.0749	.0735	.0721	.0708	.0694	.0681
1.3	.0968	.0951	.0934	.0918	.0901	.0885	.0869	.0853	.0838	.0823
1.2	.1151	.1131	.1112	.1093	.1075	.1056	.1038	.1020	.1003	.0985
1.1	.1357	.1335	.1314	.1292	.1271	.1251	.1230	.1210	.1190	.1170
1.0	.1587	.1562	.1539	.1515	.1492	.1469	.1446	.1423	.1401	.1379
0.9	.1841	.1814	.1788	.1762	.1736	.1711	.1685	.1660	.1635	.1611
0.8	.2119	.2090	.2061	.2033	.2005	.1977	.1949	.1922	.1894	.1867
0.7	.2420	.2389	.2358	.2327	.2297	.2266	.2236	.2206	.2177	.2148
0.6	.2743	.2709	.2676	.2643	.2611	.2578	.2546	.2514	.2483	.2451
0.5	.3085	.3050	.3015	.2981	.2946	.2912	.2877	.2843	.2810	.2776
0.4	.3446	.3409	.3372	.3336	.3300	.3264	.3228	.3192	.3156	.3121
0.3	.3281	.3783	.3745	.3707	.3669	.3632	.3594	.3557	.3520	.3483
0.2	.4207	.4168	.4129	.4090	.4052	.4013	.3974	.3936	.3897	.3859
0.1	.4602	.4562	.4522	.4483	.4443	.4404	.4364	.4325	.4286	.4247
0.0	.5000	.4960	.4920	.4880	.4840	.4801	.4761	.4721	.4681	.4641

What do we learn?


- Calculate Z_{upper} and Z_{lower}

$$Z_{upper} = 2.65 \rightarrow 0.0040 \rightarrow 0.4\%$$

$$Z_{lower} = 3.16 \rightarrow 0.00079 \rightarrow 0.08\%$$



We expect 0.4% + 0.08% of data to be outside the specification limits.

5. Efficiency & Process Improvement




Choose
One











Choose One

Oh...Now I get it




White Beads Red Beads Six-Way Analysis





Describe the Process:




We have a process that is behaving predictably with only common-cause variation present.

Our Cp being ~ 1.00 means that our specification spread is about the same size as our process spread.


Based on these specs, though, our data is not perfectly centered around the target.

Therefore, our process spread bleeds beyond the specification spread. We are incapable of meeting the requirements of our customer.





How would you improve our Capability?



Option 1:

Reduce sources of variation. Invest energy in the process to find ways to more consistently pull 7 (or nearly 7) red beads.

Option 2:

Loosen the specifications.





Notice what we're not talking about?

Inspect more parts

Contain the Defects


Hire more inspectors



It's all about Prevention!



In Summary





Thank you, Quality Digest!



<https://community.pqsystems.com/>

www.pqsystems.com | 800-777-3020 | sales@pqsystems.com